




Carriage photos




Correct way to load film
11 Jun 2026 11:20




Incorrect way to load film
11 Jun 2026 11:20



Machine to close to pillar to allow for maintenance of the internals of the machine
11 Jun 2026 11:20



Moved and repositioned
11 Jun 2026 11:20



Stretch chain all okay
11 Jun 2026 11:21



All okay
11 Jun 2026 11:21



Top handle plastic broken, still functional
11 Jun 2026 11:21

Stretch Assembly